



07/20/2021

Division of Water and Waste Management
West Virginia Department Of Environmental Protection
601 57th Street
SE Charleston
WV 25304.

To Whom it may concern:

Attached are ROCKWOOL's second quarter monitoring results for the RAN5 facility. There was no discharge recorded for Outlet 001 as a combination of several circumstances. The forebay of the Stormwater Management Pond was cleaned out so water in this area was conserved and pumped into the Reuse Pond and utilized within the facility process. Similarly the valve on the outlet pipe is undergoing repair so stored water from the main portion of the Stormwater Management Pond was also pumped into the Reuse Pond and used within the facility process.

For Outlet 002 the sample indicated that the benchmark values for iron and aluminium were exceeded. All other parameters were below benchmark values. While the facility is currently monitor only, RAN5 reviewed the site conditions to assess potential sources. It appears that the results appears that the results may potentially be related to land disturbance still undergoing stabilization within the drainage area and the bio-retention area soil layer and planting still being completed. The disturbed areas were seeded and mulched in June and germination and improvement in vegetated coverage of these areas is expected in the third quarter.

Please contact Ryan Durrill at ryan.durrill@rockwool.com if you have any questions.

Sincerely,


Ryan Durrill
SHEQ Manager