	T				T	T		
PERMIT NUMBER		INSPE	7	1	MINE		BL	ASTING
	DATE	TIME		TYPE	STATUS	PHOTOS	Last 30 Days	? Ins. Req'o
Q200189	03/11/2020	11:00	CC	Р	AQ	No	Yes	Yes
PERMITTEE NA	ME		BARDON, INC	D.		MSI	-IA# 00	0000
OPERATOR NA	ME					MR-19 D	ATE	
NPDES #	WV0005622	NPDES	EXPR DATE	01/17/202	4 PEI	 RMIT EXPR D	OATE 05/04	4/2021
PERMIT	TOTAL		-		ANCIL-			
ACRES 999	6.61 DISTBD _	730.00	RECLMD	20.00	LARY		UNRECLMD	710
DATES: PHI_	PH	II	LA	ST AUG SEE	ED	M	R-8	
LAST INSP DATE	01/28/2020 TYP I	E CS	BOND	4	BONDED CRES	005 01	JR CUI R# ⁰ RE\	
EXPR DATES: I	ASS 11 10 (I	-	RESP PLAN		_	1.0	BLAST AD	
	S)==> PERMIT REV			T 4.05			ALEXANDER OF ANY COLUMN	
THE OOLD (TIK			.50 INSPEC	T 1.25	TRAVE	L 6.00	REPORT	1.00
ISPECTION COM								
illville Quarry:	HPU SEV issued	on this da	ate under the	NPDES pe	rmit. Comp	plaint docur	nented in citiz	zen's
ervices under ti	he mining permit.							
NFORCEMENT ST	TANDARD	EVALU	ATION VIO#	ENFORC	EMENT STA	NDARD	EVALU	JATION VIC
00 Distance Pr	ohibited			0200	Exceeding Lin	nits		
300 Signs and N	/larkers			0400	Sediment Cor	ntrol		
500 Design Cert	tification			0600 I	Effluent Limits	S		
	ter			0800	Ground Water	•		
_	ocedures			1000 I	Haul Roads			
	oundments				-	ng		
	ading				Reclamation S	Schedule		
	n Requirements					cess Spoil		
-	mination					oil Disposal		
	Land Use					g Temporarily.		
	g /Toxic Material Operator					erations		
	and Drainage Control					ons		
	Plan					Control rent		
	rrent					ns		NA .
ATER QUALITY TE				0000	other condition		CO	IVI
Structure ID	Outfall	рН	Fe	Mn	Al	No Flow	Not Const.	Topodos
		P		14111		INOTIOW	NOT CONST.	Treatment
								1
MITH COMPANY	DEDDESENTATIVE	Andy Wri	ight]
AUTH. COMPANY	REPRESENTATIVE _	7 tildy VVII						-
DELIVERY METHO	DD / DATE TIME	Mail 3/12	/2020 12:00:00					
ERTIFIED MAIL N	NUMBER							
DDRESS 6401	GOLDEN TRIANGLE	DR, SUITE	A00, GREENBE	LT. MD 2077	0-0000			
VV DEP REP Je		11	7					
VV DEPREP Je	socioa A Dauzuk /	/ /-	6					

ERIS

NPDES				INSPECTION	ON		
NUMBER	LATITUDE	LONGITUDE	DATE	TIME	REASON	TYPE	PHOTOS
WV0005622	39 ° 16 ' 54 "	77 ° 47 ' 57 "	03/11/2020	11:00	CC	RI	Yes

PERMITTEE NAME	BAR	NPDES EXP DA	ATE 01/17/2024		
ASSOC. PERMITS Q200189					
INSP DATE 01/28/2020 TYPE	RI	CUR NPR#	CUR NPM:	CUR # NPT#	
TIME USED (HRS)==> PERMIT REVIEW	0.50	INSPECT 1.2	TRAV	EL 6.00 REF	PORT 1.00
AREAS EVALUATED: PERMIT X	FA	CILITY SITE REVIEW	/ <u>X</u>	EFFLUENT/RECEIVING	WATERS X
RECORDS/REPORTS N/A	SELF-MOI	NITORING PROGRAI	N/A	COMPLIANCE SCI	HEDULES N/A
OPERATIONS MAINTENANCE X		STORMWATER	X	SAMPLING	G DONE? Yes

INSPECTION COMMENTS

Millville Quarry: Awaiting lab results. Inspector was contacted by a citizen concerned about material entering the Shenandoah River from the Millville Quarry. Photographs were emailed to the inspector by the citizen, and an inspection date was set. On 3/11/2020, the Inspector and Inspector in Training Jordan Taylor met the citizen near the permit to investigate her concerns. A lab sample of outlet 001 was taken. After travelling downstream, grey sludge was observed in a ditch which flows into the river. The material was tracked up to a road culvert, and to the permit boundary. Citizen did not wish to accompany the inspectors

SEV S	TANDARD	EVALUATION	SEV#	SEV STANDARD	EVALUATION	SEV#
A0012	Effluent Violation			A0013 Failed Toxicity Test		
A0015	Unauthorized Discharge			A0016 Reported Fish Kill		
A0022	Narrative Effluent Violation			A0023 Industrial Spill		
B0019	Best Management Practice Deficie			B0020 Improper Operation and Maintena		
B0026	Failure to Allow Entry			B0028 Failure to Implement SPCC Plan		
B0041	Failure to Maintain Records			B0042 Violation of a milestone in an orde		
C0021	Failure to Monitor for Toxicity Requ			D0011 Discharge Without a Valid Permit.		
D0013	Unapproved Operation			D0015 Failure to Pay Fees		
D0016	Fail to Submit Timely Permit Rene			D0017 Violation Specified in Comment	SEV Issued	3
E0014	Noncompl. w/ Sect. 308 Info Requ			E0016 Failure to Submit Req. Report (No		
E0017	Failure to Notify					

WATER QUALITY TESTS

Outfall	рН	Fe	Mn	Al	No Flow	Not Const.	Treatment
001	8.5	0	0				No

AUTH. COMPANY REPRESENTATIVE Andy Wright	
DELIVERY METHOD / DATE TIME	COMPLETION DATE TIME 3/11/2020 12:15:00
CERTIFIED MAIL NUMBER	
ADDRESS 6401 GOLDEN TRIANGLE DR, SUITE 400, GREENBELT, MD 20	0770-0000
WV DEP REP. Jessica A Baczuk	
_/	

MR-6HPE ERIS

West Virginia Department of Environmental Protection MR-6HPE HYDROLOGIC PROTECTION UNIT INSPECTION (EPA) REPORT

Page 2 of 2

NPDES				INSPECTI	ON		
NUMBER	LATITUDE	LONGITUDE	DATE	TIME	REASON	TYPE	рнотоѕ
WV0005622	39 ° 16 ' 54 "	77 ° 47 ' 57 "	03/11/2020	11:00	СС	RI	Yes

COMMENT (cont.)

onsite. Inspectors then went to the permitted area to track where the material had originated from. The material was piled near the railroad tracks near the permit boundary. Evidence of the material being washed down a ditch and into the culvert was observed. Company Representative Andy Wright then travelled to the area to assess the situation. Inspector was informed that the problem should be fixed by the end of the week, weather permitting. SEV issued at this time for conditions not allowable in waters of the state due to the buildup and deposition of limestone sludge in the Shenandoah River.

MR-15HPE

West Virginia Department Of Environmental Protection

Page 1 of 1

ERIS

MR-HP15E HYDROLOGIC PROTECTION UNIT SINGLE EVENT VIOLATION


NPDES	ORIGINAL IN	SPECTION	SEV COI	DE DATA	SE	INSP ID		
NUMBER	DATE	TIME	FORM# SEV CODE		DATE	TIME	SEV#	NUMBER
WV0005622	03/11/2020	11:00	HP6E	D0017	03/11/2020	12:00	3	1067

PERMITTEE NAME BARDON, INC. Assoc. Permits Q200189 Whereas an inspection of the above operation by the undersigned Authorized Representative of the Director was completed on the 11th day of March, 2020. The inspection revealed a violation of the provisions of Chapter 22, Article 11 of the Code of West Virginia. You are hereby notified that you are in violation of the provisions listed below. **WV CODE** Reg 47-22-11-4(a) 2-3.2.b [DOV] Description of Violation: Permittee allowed grey limestone sludge to leave the permitted area through a box culvert, which then travelled down a ditch, and into the Shenandoah River. The sludge was deposited along the streambed near the riverbank. SEV issued at this time for conditions not allowable in waters of the state. [REM] Remedial Measures: Permittee must remove limestone sludge from the ditch leaving the permitted area, and fix the berm along the railroad tracks to prevent material from leaving the site. MUST BE CORRECTED WITHIN 20 DAYS OF ISSUANCE OR YOUR PERMIT MAY BE SUBJECT TO PENALTIES. REVOCATION, SUSPENSION OR MODIFICATION. **NOV** Issued ✓ Resulted in Off-Site Impact AUTH. COMPANY REPRESENTATIVE Andy Wright DELIVERY METHOD / DATE TIME Certified 3/12/2020 12:00:00 **CERTIFIED MAIL NUMBER** 7016 3010 0000 7853 1619 ADDRESS 6401 GOLDEN TRIANGLE DR, SUITE 400, GREENBELT, MD 20770-0000 WV DEP REP. Jessica A Baczuk **Austin Caperton** 03/12/2020 [Secretary, Department of Environmental Protection] [WV DEP Rep/Date]

Contact ______ Jessica A Baczuk _____ at (304) _____ upon completion. Failure to complete the above measures within the above time period may result in a Cessation Order or revocation of the permit and forfeiture of the performance bond.















MR-35 ERIS

West Virginia Department of Environmental Protection DIVISION OF MINING AND RECLAMATION COMPLAINT INVESTIGATION

Page 1 of 2

PERMIT	COMPLAINT INITIAL COMPLAINTANT CONTACT									
NUMBER	DATE	TIME	DATE	TIME	COMMENT	rs:				
Q200189	03/06/2020	10:00	03/06/2020	10:56						
METHOD OF CO	MPLAINT I	N PERSON	LETTER	но	TLINE [✓ PHONE	EMAIL	OTHER		
TYPE OF COMPL	TYPE OF COMPLAINT V NON-BLASTING BLASTING									
	NON-CONFIDENTIAL									
CITIZEN NAME: MALONEY, LORI										
ADDRESS:						PHONE:(H)		(140) (047) 754 0040		
CITIZEN TO ACCO	OMPANY: ✓ Y	ES NO	DATE/TIME	CITIZEN AD	WISED OF D			(W) (917)-751-2616		
2000	Accompany Fo		DATE/TIME	CITIZEN AD	VISED OF R	IGHT TO ACC	COMPANY:	03/11/2020 11:00:00		
NATURE OF COMP	PLAINT									
Citizen comp	lained abo	ut slud	ge in the	Shenando	oah Rive	r. She	is associat	ted with the		
Jefferson Co	ounty Found	lation								
CONTRACT BLAS	TING FIRM									
BLASTER NAME (CERT #)										
DISTANCE TO NE		BLAST	GPS LOCATION	LAT			LONG			
PROT. STRUCT	. (ft)						Y			
PERMITTEE NAME	BARDON, INC	D								
OPERATOR NAME										
RECEIVING STREAM			FICE HARPERS	FERRY	_ LOCATIO					
RECEIVING STREAM						NPDES	NUMBER			
COMPLAINT STATE	JS INIT	ΓIAL ✓	OPEN	TERMINAT	ED	UNSUBSTA	ANTIATED	WITHDRAWN		
INVESTIGATION D	ATE03/	11/2020	DATE R	IGHT TO RI	EVIEW ADVI	SED	03/11/2020			
INSPECT DATE	03/11/2020 T II	VIE 11:00	:00 FORM #		ENE OTO					
mor Eor BAIL		11.00	FORIWI #		_ ENF STD		VIOL #			
FACILITY										
NVESTIGATION RE	SULTS									
When citizen	was first	contact	ed, she ex	pressed	concern	about m	aterial lea	aving the		
quarry's bond	ded area ar	nd enter	ing the Sh	enandoa	h River,	and tha	t outlet 00	01 appeared		
pank, but did	not with	to go o	mpany the nto the qu	arry it	or durin self. Up	ig the in on arriv	vestigation ing at out	n of the river		
DISTRIBUTED TO:	Lori Maloney									
PROVIDED TO CIT	IZEN: DEL. ME	THOD / DAT	E TIME Mail 3/	12/2020 12:0	00:00					
	CERTIFII	ED MAIL#_	1		·					
WV DEP REP	ssica A Baczuk	()-1	Da /				DATE _	03/12/2020		

MR-35 ERIS

West Virginia Department of Environmental Protection DIVISION OF MINING AND RECLAMATION COMPLAINT INVESTIGATION

Page 2 of 2

PERMIT	COMPLA	COMPLAINT			INITIAL COMPLAINTANT CONTACT					
NUMBER	DATE	TIME	DATE	TIME	COMMENTS:					
Q200189	03/06/2020	10:00	03/06/2020	10:56						
METHOD OF CO	MPLAINT [] IN	PERSON	LETTER	П НО	TLINE 🗸	PHONE	EMAIL	OTHER		
TYPE OF COMPL	AINT V NON	I-BLASTING	BLASTING	}						

INVESTIGATION RESULTS (cont.)

inspector pulled a lab sample. The discharge did not appear cloudy, but there was residual sedimentation at the discharge from a violation issued the previous summer. After walking downstream from the outlet about 50 yards, grey sludge was observed entering the river. The material was entering the stream, and being deposited along the river bank for approximately 10 feet. After tracking the material up a ditch and through a road culvert to the railroad tracks along the permit boundary, the inspector and citizen parted ways. The inspector travelled on site and observed a large deposit of sludge like material beside the railroad tracks. It appeared that a rainstorm had washed the material down the ditch and off of the permitted area. Company Representative Andy Wright was notified, and joined the inspector at the location. The representative was told a violation would be issued, and that the problem needed to be fixed. Mr. Wright said the company would fix it within a week.