



06/29/2021

Mr. Keith R. Allison

Environmental Inspector
WV Department of Environmental Protection
Division of Water and Waste Management
22288 Northwestern Pk
Romney, WV 26757.

Dear **Mr. Allison**,

The ROCKWOOL-Ranson facility would like to inform you of a project that will be completed onsite. As part of our routine preventative maintenance and facility inspection activities we have identified that a fire hydrant located on the north end of the facility at times retains minimal amounts of water at the perimeter.

Because the fire hydrant is located on an impermeable surface, we do not believe that the retention of water presents any risk to the environment. But, to maintain systems in good order, we intend to excavate the specified location and investigate the possible presence of water so that repairs can be completed as required.

Please do not hesitate to contact me directly should you have any questions.

Sincerely,

Ryan Durrill
SHEQ Manager