



05/24/2021

**Mr. Keith R. Allison**

Environmental Inspector  
WV Department of Environmental Protection  
Division of Water and Waste Management  
22288 Northwestern Pk  
Romney, WV 26757.

Dear **Mr. Allison**,

The RAN5 facility is sending this communication to keep you informed on some maintenance that will be taking place on the outlet system for the Stormwater Management Basin. This work will take place over the next several days. During a routine inspection of the facility, the butterfly valve located on the discharge pipe approximately 110 feet from the pond riser structure was exercised. It was noted that the valve does have motion and is currently open and the pond is functioning. The observed condition in question is that the valve does not appear to be moving through its entire range of motion.

RAN5 has tasked a local contractor to excavate around the valve and provide access to inspect these components. This will occur during the upcoming several days (starting Friday May 21) while the weather is forecast to have minimal chances of precipitation. Temporary access to the pipe will most likely be necessary through removal of a section of the top of the pipe. The flow line and sides of the discharge line will remain in place. RAN5 will update you on final actions taken to access and inspect the pipe and valve. RAN5 will also inform you of repairs/maintenance conducted and schedule for such repairs if they cannot be promptly completed.

Do not hesitate to contact Ryan Durrill at 304-830-6464 should you have any questions.

Sincerely,

A handwritten signature in black ink that reads 'Kimberly Burgess' in a cursive script.

**Kimberly Burgess**  
**SHE Director – North America**